Repair vs. Replacement

How Your Facility Can Reduce Risk, Save Time And Money By Learning The Basics

#jasboAC22



Introductions

Doug Renkosik, Moderator *Director, Operations and Maintenance*

Jim O'Callaghan, Speaker Managing Director, ACR, Inc.

#iasboAC22

Bob Smolka, AMRT, CDS, FSRT, CMR, Speaker Production Director, ACR, Inc.



A | C | R RESTORES

A C R RESTORES



Jim O'Callaghan Managing Director, ACR, Inc. Presenter

- 35+ years in restoration
- Industry subject matter expert
- Systems & Process
- Emergency Planning
- Healthcare Consulting

#iasboAC22

30 Years in the Education Sector





Bob Smolka, Production Manager, ACR, Inc. Presenter

- 30+ years in restoration
- CMR, AMRT, CDS
- Certified Mold Remediation trainer for:
 - CAMICB
 - IL Department of Insurance

#iasboAC22

SEIU Local 1





Course Overview

- 3 keys to a successful restoration outcome
- Understand the "disrupters" in your facility and how they impact time, risk and cost
- Why having a risk management plan in place is vital
- What is operational continuity?
- 4 steps your restoration contractor should always follow
- 3 local case studies

#jasboAC22



Repair vs. Replacement 3 Keys to Success



#iasboAC22

RISK You can AVOID, ACCEPT, MITIGATE or TRANSFER Environment Resources People



Repair vs. Replacement 3 Keys to Success



#iasboAC22

COST

Exceed limits Supplements Business Interruption Lost Revenue Reserve



Repair vs. Replacement 3 Keys to Success



#iasboAC22

SPEED (or "TIME") Too Fast or Too Slow Forward Acceleration Timelines Code Upgrades Engineering Reports Environmental



Navigating Facility Disrupters




#jasboAC22

Maintenance & custodial staffing issues Winter freeze Facilities reopening Supply chain issues Changing COVID-19 protocols Water damage Convective storms (thunderstorms)



Emergencies By The Numbers




2022 CONFERENCE

#iasboAC22


Commercial Insurance Claims & Lost Revenue 2020-2052 Projected

- 751,000 in 2020
- 769,000 projected in 2022
- 992,000 projected in 2052
- 29% Increase from 2022 to 2052



STRONGER TOGETHER. SMARTER

2020 Commercial Property Insurance Report by Percentage Of Claims



Water is Often the Culprit



"What if we don't change anything at all ... and something magical just happens."

#iasboAC22

"Water damage is one of the largest loss causes we deal with in the commercial insurance industry, yet only a small percentage of clients have a formal Water Damage Prevention Plan in place." —

Patrick Daley, Head of Large Property with The Hartford



2022 Projected CHICAGO Area Commercial Claims Lost Revenue vs Lost Days



#jasboAC22

22,000 Water Claims
\$448 Million lost revenue
88,660 Facility days lost



Operational Continuity

op·er·a·tion·al ◀ adjective \-shnal, -sha-n*\ : ready for use : able to be used : of or relating to the operation of a business or machine con·ti·nu·i·ty ◀ noun \kan-ta-nù-a-tē, -nyù-\ : the quality of something that does not stop or change as time passes : a continuous quality

: something that is the same or similar in two or more things and provides a connection between them

Ability of the key operations of a firm to continue without stoppage, **irrespective** of the adverse circumstances or events."

#jasboAC22



Maintaining Operational Continuity In The Restoration Phase SAVES MONEY




#jasboAC22

- Reducing operational expense and loss of use
- Concentrating on restoration vs. tear-out and replacement
- Driven by systems, process, planning



Preparation And Planning Pre-select a mitigation vendor



#iasboAC22

The worst possible time to find a quality mitigation vendor is *during* an emergency.

- Assess experience
- Check credentials
- Upfront contract







Preparation And Planning

Assess your mitigation vendor and seek certifications that maximize results

CR: RIA Certified Restorer **WLS**: RIA Water Loss Specialist **MWR**: IICRC Master Water Restorer **MSR**: IICRC Master Fire & Smoke Restorer **ICRA:** Certified Healthcare Remediator Supervisor



#iasboAC22



STRONGER TOGETHER. SMARTER



Preparation And Planning

Share the Risk

INTERNALLY

PrincipalSuperintendentBuildings & Grounds

#iasboAC22


EXTERNALLY

- Insurance carrier
- Suppliers & Vendors
- Restoration Contractor





Emergency Response and Mitigation



Emergency Response and Mitigation


4 steps you and your contractor should take to save money

Assess Communicate Isolate Mitigate

#iasboAC22



SHOW AND TELL #1



#iasboAC22

vs.





Case Study #1 Chicago Area Community College February 2020

#iasboAC22



The Event

Toilet overflow on the 2nd floor

#jasboAC22

- Auditorium and 15 classrooms affected
- Double drywall
- Limited power on 2nd floor due to electrical panel underwater
- Discovered fungal issues unrelated to loss
- Many built-in cabinets adjacent to wet drywall; in some cases, cabinets obstructed the ability to use meters on walls







Oct 15,2020 03:48:10 PM

	19 L
	HE SHOT DESIGNATION
- Caller - Andrews	being has seen and
And income of the local data	The second second second
The second	
Desire in the local data	· · · · · · · · · · · · · · · · · · ·
-	- Andrew -

Oct 10,2020 03:07:44 PM







The Outcome

- Able to save the drywall
- Base dried, removed and reused (School decided to replace)
- All cabinets were saved
- •Used vents to create air movement to dry more quickly
- No long-term relocation due to reconstruction (students)
- Job completed in 12 days

#jasboAC22

•Mitigation cost was \$38,907.68

vs Cost/time of replacement



SMART

Case Study #2 North Suburban Middle School November 2021

#iasboAC22



The Event

Received call at 2:00 AM
Floor scrubber caught fire in vestibule, setting off sprinkler system.
1 hallway and 6 classrooms affected
No soot found initially, odor and water in classrooms

 Students arriving to school within 5 hours of event

#iasboAC22





FOGETHER. SMARTER

Nov 05,2021 07:09:59 PM

-97

10

-

a











The Outcome

- Performed work from 2:00 AM-7:00 AM and 6:00 PM-9:00 PM
- School staff began immediately extracting water
- Removed 2 layers of cove base
- Hepa Vac and sponge clean walls & windows in vestibule
- 1 day
- Zero disruption to students

#jasboAC22

- Total cost \$9642.65 to mitigate
- (\$11,570.38----ceiling tile, carpeting, toe kicks, etc.)



SHOW AND TELL #2



#iasboAC22



Case Study #3 Northwest Suburban High School November 2020

#iasboAC22



The Event

- Gatorade poured onto gym floor
- Two small sections of floor were wet and cupped
- One section of floor was completely saturated affecting the floor and the plywood subflooring

#iasboAC22













The Outcome

Set pins within 24 hours on February 6 Created containments to reduce drying area Used inject-a-dry system Added a heater ducted underneath floor Job completed on February 11 •Floor saved for a cost of \$8491.83 vs \$75,000 + overall replacement time Maintained operational continuity

#jasboAC22



Maintenance Considerations



#iasboAC22

Freezing HVAC coils

- Frozen water pipes
- Checking for leaks, standing water etc.
- Exterior air dampers on air handlers
- Boiler maintenance
- Steam valves
- Snow blocking exterior vents



Do You Have a Plan?

"An ounce of prevention is worth a pound of cure"




#iasboAC22

-Benjamin Franklin



Emergency Response Agreement



#iasboAC22



Final Thoughts



Time is of the essence

Select vendors *before* an event happens

ALWAYS know who in your facility is in charge during an emergency

Don't forget that Risk management directly affects the bottom line.



Questions and Answers

We thank you for your time!





Presenters:

PANELISTS:

Bob Smolka, Production Director; ACR, Inc. (847) 417-5310; <u>Bsmolka@acrrestores.com</u>

Jim O'Callaghan, Managing Director; ACR, Inc. (708) 417-5720; Jocallaghan@acrrestores.com

A C R RESTORES

#iasboAC22

551 Glenn Avenue Wheeling, Illinois 60090 (866) 645-1165 ACRrestores.com

MODERATOR:

Doug Renkosik, Director, Operations and Maintenance; D158 (847) 659-6161; <u>drenkosik@district158.org</u>

